

GS3 2630 - Clearing Data



How to clear data from a GS3 2630

Select Main Menu on bottom right

GreenStar™ 3 2630 Display

Controller is not yet available...

Input 1

Input 2

Input 3


Recording SF3

P3:37 pm


2 Select "GreenStar" or the softkey that says "GS3"




3 Select "GS3" softkey in the top right of the screen




4 Select "Memory" tab at the top of the screen



5 Select "Erase Data"



6 Select which option the Operator needs.



- Selecting "Transfer Log" will remove the files that are to be transferred to the Operator's Operations Center account
- Selecting "Documentation Data" will remove agronomic data that has been recorded in the past. It will leave data like the Operator's Client, Farm, Field, equipment info, etc.
- ! Selecting "All Data" will reset the display to Factory Defaults

7 Once Operator has made a selection, select "Begin Removal"

