

# GEN4



MIDWEST  
MACHINERY CO



## CREATING GUIDANCE LINES


How to create guidance lines.

# Gen4 - Creating Guidance Lines


- 1 Select the "Menu" button in the bottom right of the screen



2 Select "Applications" on the left side of the screen




3 Select "AutoTrac Guidance"




4

Notice the AutoTrac Master cannot be turned on if there is no guidance line selected




5


Select "Set Track" on the right side of the screen



6 Select "New Track"



7 In the "Straight Track" section, select "A + B Method"



8 Name the Track

4600 CommandCenter™

**New Guidance Track** ⓘ

**Track Name**  
Track 1

**Method:**  
A + B

**Modified:**  
12-29-2022 03:08 PM

**Field**  
South 40

**Guidance Line Calculation**  
John Deere

✕ Cancel **OK**

9 Select "OK"

4600 CommandCenter™

**New Guidance Track** ⓘ

**Track Name**  
Track 1

**Method:**  
A + B


**Modified:**  
12-29-2022 03:08 PM

**Field**  
South 40

**Guidance Line Calculation**  
John Deere

✕ Cancel **OK**

- 10 Select "Set A" and move the machine forward




- 11 Select "Set B." Once hitting this, system will snap a line directly between Point A and Point B.



12

Once a line has been established, the AutoTrac button can be pressed to enable AutoTrac




## Gen4 AutoTrac Troubleshooting



13 Click Menu



14 Click System




15 Click the Diagnostics Center



16 Click Guidance - AutoTrac



17 For additional information Click the Help Icon



18 For additional Help Read the AutoTrac Health.

